

## Table of Contents

<b>Preface . . . . .</b>	<b>xi</b>
<b>Acknowledgements . . . . .</b>	<b>xv</b>
<b>An Historical Introduction: The Discovery of X-rays and the First Studies in X-ray Diffraction . . . . .</b>	<b>xvii</b>
<b>Part 1. Basic Theoretical Elements, Instrumentation and Classical Interpretations of the Results . . . . .</b>	<b>1</b>
<b>Chapter 1. Kinematic and Geometric Theories of X-ray Diffraction . . . . .</b>	<b>3</b>
1.1. Scattering by an atom . . . . .	3
1.1.1. Scattering by a free electron . . . . .	3
1.1.1.1. Coherent scattering: the Thomson formula . . . . .	3
1.1.1.2. Incoherent scattering: Compton scattering [COM 23] . . . . .	6
1.1.2. Scattering by a bound electron . . . . .	8
1.1.3. Scattering by a multi-electron atom . . . . .	11
1.2. Diffraction by an ideal crystal . . . . .	14
1.2.1. A few elements of crystallography . . . . .	14
1.2.1.1. Direct lattice . . . . .	14
1.2.1.2. Reciprocal lattice . . . . .	16
1.2.2. Kinematic theory of diffraction . . . . .	17
1.2.2.1. Diffracted amplitude: structure factor and form factor . . . . .	17
1.2.2.2. Diffracted intensity . . . . .	18
1.2.2.3. Laue conditions [FRI 12] . . . . .	22
1.2.3. Geometric theory of diffraction . . . . .	23
1.2.3.1. Laue conditions . . . . .	23
1.2.3.2. Bragg's law [BRA 13b, BRA 15] . . . . .	24
1.2.3.3. The Ewald sphere . . . . .	26

1.3. Diffraction by an ideally imperfect crystal . . . . .	28
1.4. Diffraction by a polycrystalline sample . . . . .	33
<b>Chapter 2. Instrumentation used for X-ray Diffraction . . . . .</b>	<b>39</b>
2.1. The different elements of a diffractometer . . . . .	39
2.1.1. X-ray sources . . . . .	39
2.1.1.1. Crookes tubes . . . . .	41
2.1.1.2. Coolidge tubes . . . . .	42
2.1.1.3. High intensity tubes . . . . .	47
2.1.1.4. Synchrotron radiation . . . . .	49
2.1.2. Filters and monochromator crystals . . . . .	52
2.1.2.1. Filters . . . . .	52
2.1.2.2. Monochromator crystals . . . . .	55
2.1.2.3. Multi-layered monochromators or mirrors . . . . .	59
2.1.3. Detectors . . . . .	62
2.1.3.1. Photographic film . . . . .	62
2.1.3.2. Gas detectors . . . . .	63
2.1.3.3. Solid detectors . . . . .	68
2.2. Diffractometers designed for the study of powdered or bulk polycrystalline samples . . . . .	72
2.2.1. The Debye-Scherrer and Hull diffractometer . . . . .	73
2.2.1.1. The traditional Debye-Scherrer and Hull diffractometer . . . . .	74
2.2.1.2. The modern Debye-Scherrer and Hill diffractometer: use of position sensitive detectors . . . . .	76
2.2.2. Focusing diffractometers: Seeman and Bohlin diffractometers . . . . .	87
2.2.2.1. Principle . . . . .	87
2.2.2.2. The different configurations . . . . .	88
2.2.3. Bragg-Brentano diffractometers . . . . .	94
2.2.3.1. Principle . . . . .	94
2.2.3.2. Description of the diffractometer; path of the X-ray beams . . . . .	97
2.2.3.3. Depth and irradiated volume . . . . .	103
2.2.4. Parallel geometry diffractometers . . . . .	104
2.2.5. Diffractometers equipped with plane detectors . . . . .	109
2.3. Diffractometers designed for the study of thin films . . . . .	110
2.3.1. Fundamental problem . . . . .	110
2.3.1.1. Introduction . . . . .	110
2.3.1.2. Penetration depth and diffracted intensity . . . . .	111
2.3.2. Conventional diffractometers designed for the study of polycrystalline films . . . . .	116
2.3.3. Systems designed for the study of textured layers . . . . .	118

2.3.4. High resolution diffractometers designed for the study of epitaxial films . . . . .	120
2.3.5. Sample holder . . . . .	123
2.4. An introduction to surface diffractometry . . . . .	125
<b>Chapter 3. Data Processing, Extracting Information . . . . .</b>	<b>127</b>
3.1. Peak profile: instrumental aberrations . . . . .	129
3.1.1. X-ray source: $g_1(\epsilon)$ . . . . .	130
3.1.2. Slit: $g_2(\epsilon)$ . . . . .	130
3.1.3. Spectral width: $g_3(\epsilon)$ . . . . .	131
3.1.4. Axial divergence: $g_4(\epsilon)$ . . . . .	131
3.1.5. Transparency of the sample: $g_5(\epsilon)$ . . . . .	133
3.2. Instrumental resolution function . . . . .	135
3.3. Fitting diffraction patterns . . . . .	138
3.3.1. Fitting functions . . . . .	138
3.3.1.1. Functions chosen <i>a priori</i> . . . . .	138
3.3.1.2. Functions calculated from the physical characteristics of the diffractometer . . . . .	143
3.3.2. Quality standards . . . . .	144
3.3.3. Peak by peak fitting . . . . .	145
3.3.4. Whole pattern fitting . . . . .	147
3.3.4.1. Fitting with cell constraints . . . . .	147
3.3.4.2. Structural simulation: the Rietveld method . . . . .	147
3.4. The resulting characteristic values . . . . .	150
3.4.1. Position . . . . .	151
3.4.2. Integrated intensity . . . . .	152
3.4.3. Intensity distribution: peak profiles . . . . .	153
<b>Chapter 4. Interpreting the Results . . . . .</b>	<b>155</b>
4.1. Phase identification . . . . .	155
4.2. Quantitative phase analysis . . . . .	158
4.2.1. Experimental problems . . . . .	158
4.2.1.1. Number of diffracting grains and preferential orientation . . . . .	158
4.2.1.2. Differential absorption . . . . .	161
4.2.2. Methods for extracting the integrated intensity . . . . .	162
4.2.2.1. Measurements based on peak by peak fitting . . . . .	162
4.2.2.2. Measurements based on the whole fitting of the diagram . . . . .	163
4.2.3. Quantitative analysis procedures . . . . .	165
4.2.3.1. The direct method . . . . .	165
4.2.3.2. External control samples . . . . .	166
4.2.3.3. Internal control samples . . . . .	166

4.3. Identification of the crystal system and refinement of the cell parameters . . . . .	167
4.3.1. Identification of the crystal system: indexing . . . . .	167
4.3.2. Refinement of the cell parameters . . . . .	171
4.4. Introduction to structural analysis . . . . .	172
4.4.1. General ideas and fundamental concepts . . . . .	173
4.4.1.1. Relation between the integrated intensity and the electron density . . . . .	173
4.4.1.2. Structural analysis . . . . .	175
4.4.1.3. The Patterson function . . . . .	177
4.4.1.4. Two-dimensional representations of the electron density distribution . . . . .	180
4.4.2. Determining and refining structures based on diagrams produced with polycrystalline samples . . . . .	183
4.4.2.1. Introduction . . . . .	183
4.4.2.2. Measuring the integrated intensities and establishing a structural model. . . . .	184
4.4.2.3. Structure refinement: the Rietveld method . . . . .	185
<b>Part 2. Microstructural Analysis . . . . .</b>	<b>195</b>
<b>Chapter 5. Scattering and Diffraction on Imperfect Crystals . . . . .</b>	<b>197</b>
5.1. Punctual defects . . . . .	197
5.1.1. Case of a crystal containing randomly placed vacancies causing no relaxation . . . . .	198
5.1.2. Case of a crystal containing associated vacancies . . . . .	201
5.1.3. Effects of atom position relaxations . . . . .	203
5.2. Linear defects, dislocations . . . . .	205
5.2.1. Comments on the displacement term . . . . .	207
5.2.2. Comments on the contrast factor . . . . .	210
5.2.3. Comments on the factor $f(M)$ . . . . .	212
5.3. Planar defects . . . . .	212
5.4. Volume defects . . . . .	218
5.4.1. Size of the crystals . . . . .	218
5.4.2. Microstrains . . . . .	226
5.4.3. Effects of the grain size and of the microstrains on the peak profiles: Fourier analysis of the diffracted intensity distribution . . . . .	231
<b>Chapter 6. Microstructural Study of Randomly Oriented Polycrystalline Samples . . . . .</b>	<b>235</b>
6.1. Extracting the pure profile . . . . .	236
6.1.1. Methods based on deconvolution . . . . .	237

6.1.1.1. Constraint free deconvolution method: Stokes' method . . . . .	238
6.1.1.2. Deconvolution by iteration . . . . .	242
6.1.1.3. Stabilization methods . . . . .	244
6.1.1.4. The maximum entropy or likelihood method, and the Bayesian method . . . . .	244
6.1.1.5. Methods based on <i>a priori</i> assumptions on the profile . . . . .	245
6.1.2. Convulsive methods. . . . .	246
6.2. Microstructural study using the integral breadth method . . . . .	247
6.2.1. The Williamson-Hall method. . . . .	248
6.2.2. The modified Williamson-Hall method and Voigt function fitting .	250
6.2.3. Study of size anisotropy . . . . .	252
6.2.4. Measurement of stacking faults . . . . .	255
6.2.5. Measurements of integral breadths by whole pattern fitting . . .	257
6.3. Microstructural study by Fourier series analysis of the peak profiles .	262
6.3.1. Direct analysis: the Bertaut-Warren-Averbach method . . . . .	262
6.3.2. Indirect Fourier analysis . . . . .	268
6.4. Microstructural study based on the modeling of the diffraction peak profiles . . . . .	270
<b>Chapter 7. Microstructural Study of Thin Films . . . . .</b>	<b>275</b>
7.1. Positioning and orienting the sample . . . . .	276
7.2. Study of disoriented or textured polycrystalline films. . . . .	279
7.2.1. Films comprised of randomly oriented crystals . . . . .	279
7.2.2. Studying textured films . . . . .	285
7.2.2.1. Determining the texture . . . . .	285
7.2.2.2. Quantification of the crystallographic orientation: studying texture . . . . .	289
7.3. Studying epitaxial films . . . . .	292
7.3.1. Studying the crystallographic orientation and determining epitaxy relations . . . . .	292
7.3.1.1. Measuring the normal orientation: rocking curves . . . . .	293
7.3.1.2. Measuring the in-plane orientation: $\phi$ -scan. . . . .	295
7.3.2. Microstructural studies of epitaxial films. . . . .	300
7.3.2.1. Reciprocal space mapping and methodology. . . . .	304
7.3.2.2. Quantitative microstructural study by fitting the intensity distributions with Voigt functions . . . . .	307
7.3.2.3. Quantitative microstructural study by modeling of one-dimensional intensity distributions . . . . .	312
<b>Bibliography . . . . .</b>	<b>319</b>
<b>Index . . . . .</b>	<b>349</b>