
Contents

| | |
|--|----|
| FOREWORD | xi |
| INTRODUCTION | xv |
| CHAPTER 1. OBJECTIVES AND VALUE OF DIMENSIONAL ANALYSIS | 1 |
| 1.1. Grouping dimensional variables in the form of a set of dimensionless numbers with a precise physical sense | 4 |
| 1.2. Constructing generic models which can be used on other scales | 5 |
| 1.3. Reduce the number of experiments by providing a synthetic and physical view of the phenomena | 8 |
| 1.4. A tool for carrying out processes and assisting a reverse engineering approach. | 10 |
| CHAPTER 2. DIMENSIONAL ANALYSIS: PRINCIPLES AND METHODOLOGY | 13 |
| 2.1. Terminology and theoretical elements | 14 |
| 2.1.1. Physical quantities and measures. Dimensions and unit systems | 14 |
| 2.1.2. The principle of homogeneity | 21 |
| 2.1.3. Fundamental rules for constructing the set (or space) of dimensionless numbers associated with a physical phenomenon. | 22 |
| 2.2. From internal measures to the form of a process relationship. | 38 |

| | |
|--|-----------|
| 2.2.1. Choosing a set of internal measures suitable for the experimental program used. | 38 |
| 2.2.2. What form of mathematical relationship should be chosen to correlate the dimensionless numbers? | 39 |
| 2.3. Configuration and operating point of a system | 43 |
| 2.3.1. Definition of the configuration of the system and its links with internal measures | 43 |
| 2.3.2. Graphic representation of the operating points of a system | 46 |
| 2.3.3. Conclusion. | 48 |
| 2.4. Guided example 1: power consumption for a Newtonian fluid in a mechanically stirred tank | 49 |
| 2.4.1. List of relevant independent physical quantities | 50 |
| 2.4.2. Determining the dimensions of the physical quantities | 51 |
| 2.4.3. Application of the Vaschy–Buckingham theorem and the construction of dimensionless numbers. | 52 |
| 2.4.4. Rearrangements of dimensionless numbers. | 54 |
| 2.4.5. From internal measures to the establishment of the process relationship | 54 |
| 2.4.6. Comments | 58 |
| 2.4.7. Conclusion. | 59 |
| CHAPTER 3. PRACTICAL TOOLS FOR UNDERTAKING THE DIMENSIONAL ANALYSIS PROCESS | 61 |
| 3.1. Establishment of the list of relevant physical quantities which influence the target variable. | 61 |
| 3.1.1. Approach to adopt in order to facilitate the establishment of the list of relevant physical quantities. | 62 |
| 3.1.2. Consequences of omitting physical quantities | 66 |
| 3.1.3. Consequences of introducing a superfluous physical quantity | 69 |
| 3.1.4. Conclusion | 69 |
| 3.2. Choosing the base | 70 |
| 3.3. Some techniques for reducing the set of dimensionless numbers (configuration of the system) | 73 |

| | |
|--|-----------|
| 3.3.1. Introduction of an intermediate variable. | 74 |
| 3.3.2. Increase in the number of fundamental dimensions. | 78 |
| CHAPTER 4. DIMENSIONAL ANALYSIS OF PROCESSES INFLUENCED BY THE VARIABILITY OF PHYSICAL PROPERTIES | 85 |
| 4.1. Introduction. | 85 |
| 4.1.1. Objective. | 88 |
| 4.1.2. Approach. | 88 |
| 4.2. Influence of the material function on the process relationship and material similarity | 90 |
| 4.2.1. Definitions and notations | 90 |
| 4.2.2. Illustrating the influence of the variability of a physical property on the target internal measure | 91 |
| 4.2.3. A necessary condition for the application of a process relationship to different materials: material similarity | 94 |
| 4.3. Dimensionless material functions: standard non-dimensionalization method and invariance properties | 96 |
| 4.3.1. Influence of the reference abscissa and the non-dimensionalization method on the form of the dimensionless material function. | 96 |
| 4.3.2. Non-dimensionalization method and theory of similarity | 101 |
| 4.3.3. Standard non-dimensionalization method. | 106 |
| 4.3.4. Standard material functions with specific properties: reference-invariant standard material functions. | 120 |
| 4.4. How to construct the π – space in the case of a process involving a material with a variable physical property | 124 |
| 4.4.1. Determining the dimensionless numbers and/or physical quantities to add to the initial relevance list | 126 |
| 4.4.2. Examples. | 133 |
| 4.4.3. Relevant choice of the reference abscissa. | 143 |
| 4.5. Guided example 2. | 146 |
| 4.5.1. Pseudoplastic fluid. | 147 |
| 4.5.2. Bingham fluid. | 150 |

| | |
|---|-----|
| CHAPTER 5. DIMENSIONAL ANALYSIS: A TOOL FOR ADDRESSING PROCESS SCALE-UP ISSUES | 157 |
| 5.1. Conditions to satisfy to ensure complete similarity between the two scales: conservation of the operating point. | 157 |
| 5.1.1. Configuration of the system and operating points | 157 |
| 5.1.2. Rules of similarity | 159 |
| 5.2. Guided example 3: cooking a chicken. | 163 |
| 5.2.1. Establishing the configuration of the system | 163 |
| 5.2.2. Analysis of the configuration of the system and similarity relationship | 165 |
| 5.3. Guided example 4: power of a vertical impeller on an industrial scale | 167 |
| 5.3.1. Establishing the configuration of the system | 168 |
| 5.3.2. Analysis of the configuration of the system and similarity relationships | 168 |
| 5.3.3. Contribution of the process relationship to the scale change | 171 |
| 5.4. Guided example 5: emulsification process in an agitation tank. | 176 |
| 5.4.1. Determining the configuration of the system | 176 |
| 5.4.2. Analysis of the configuration of the system and similarity relationships | 181 |
| 5.4.3. Contribution of the process relationship in the scale change | 184 |
| 5.5. Specific case of a scale change in a process involving a material with a variable physical property (guided example 6) | 186 |
| 5.5.1. Preamble | 186 |
| 5.5.2. Guided example 6: scaling of a scraped surface heat exchanger | 187 |
| CHAPTER 6. CASE STUDIES | 197 |
| 6.1. Rehydration time for milk powder in a stirred tank | 198 |
| 6.1.1. Target variable and relevance list of independent physical quantities | 199 |
| 6.1.2. Establishing dimensionless numbers | 201 |

| | |
|--|-----|
| 6.1.3. From the configuration of the system to the establishment of the process relationship | 203 |
| 6.2. Continuous foaming by whipping | 206 |
| 6.2.1. Target variable and list of relevant independent physical quantities | 206 |
| 6.2.2. Establishing dimensionless numbers | 208 |
| 6.2.3. From the configuration of the system to establishing a process relationship | 209 |
| 6.3. Fouling of a plate heat exchanger by a milk protein solution | 213 |
| 6.3.1. Target variables and list of relevant independent physical quantities | 216 |
| 6.3.2. Establishing dimensionless numbers | 219 |
| 6.3.3. From configurational analysis to the process relationship | 222 |
| 6.4. Dry mixing of powders: mixing time and power consumption | 230 |
| 6.4.1. List of relevant physical quantities | 230 |
| 6.4.2. Establishing dimensionless numbers | 231 |
| 6.4.3. From the configuration of the system to establishing the process relationship: the advantage of introducing an intermediate variable | 233 |
| 6.4.4. Analysis of the process relationship obtained | 240 |
| 6.5. Gas–liquid mass transfer in a mechanically stirred tank containing shear-thinning fluids | 241 |
| 6.5.1. Case study with Newtonian fluids: target variable, list of relevant independent physical quantities and the configuration of the system | 242 |
| 6.5.2. Extension to shear-thinning fluids | 247 |
| 6.5.3. From the configuration of the system to establishing the process relationship | 251 |
| 6.5.4. Conclusion | 257 |
| 6.6. Ohmic heating | 257 |
| 6.6.1. Description of the problem | 258 |
| 6.6.2. Target variable and relevance list of independent physical quantities | 260 |
| 6.6.3. Establishing dimensionless numbers and the configuration of the system | 263 |
| 6.6.4. Analytical expression of the process relationship | 265 |
| 6.6.5. Validation of the process relationship | 266 |
| 6.6.6. Conclusion | 268 |

| | |
|--|-----|
| CONCLUSIONS | 269 |
| APPENDICES | 273 |
| APPENDIX 1: SHIFT RELATIONSHIPS BETWEEN SPACES OF DIMENSIONLESS NUMBERS | 275 |
| APPENDIX 2: PHYSICAL MEANING OF DIMENSIONLESS NUMBERS COMMONLY USED IN PROCESS ENGINEERING | 279 |
| APPENDIX 3: THE TRANSITIVITY PROPERTY OF THE STANDARD NON-DIMENSIONALIZATION METHOD AND ITS CONSEQUENCES ON THE MATHEMATICAL EXPRESSION OF REFERENCE-INVARIANT STANDARD DIMENSIONLESS MATERIAL FUNCTIONS (RSDMFs) | 295 |
| APPENDIX 4: CASES WHERE THE ANALYTICAL EXPRESSION OF THE MATERIAL FUNCTION IS KNOWN | 309 |
| APPENDIX 5: CASES WHERE THERE IS NO KNOWN ANALYTICAL EXPRESSION OF THE MATERIAL FUNCTION | 317 |
| APPENDIX 6: RELEVANT CHOICE OF THE REFERENCE ABSCISSA FOR NON-NEWTONIAN FLUIDS | 323 |
| BIBLIOGRAPHY | 329 |
| INDEX | 335 |