

Table of Contents

| | |
|---|----|
| Preface | ix |
| Chapter 1. Main Requirements | 1 |
| 1.1. Introduction | 1 |
| 1.2. Sinusoidal variables | 1 |
| 1.2.1. Single-phase variables | 1 |
| 1.2.2. 2-phase voltages and currents | 4 |
| 1.2.3. Balanced 3-phase sinusoidal systems | 5 |
| 1.2.4. Unbalanced 3-phase sinusoidal systems: Fortescue symmetrical components | 8 |
| 1.3. Electromagnetism | 12 |
| 1.3.1. Primary laws | 12 |
| 1.3.2. Materials and magnetic circuits. | 14 |
| 1.3.3. Inductances | 24 |
| 1.3.4. Skin effect or Kelvin effect | 29 |
| 1.3.5. Torque calculation using the virtual work principle | 30 |
| 1.4. Power electronics | 36 |
| 1.4.1. Rectifiers and naturally commutated inverters | 37 |
| 1.4.2. AC thyristor controllers | 41 |
| 1.4.3. Choppers | 44 |
| 1.4.4. Cycloconverters | 47 |
| 1.4.5. Force commutated inverters | 47 |
| Chapter 2. Introduction to Rotating Electrical Machines | 49 |
| 2.1. Introduction | 49 |
| 2.2. Main notations | 50 |
| 2.2.1. Vectors | 51 |

| | |
|--|-----------|
| 2.3. Principle of the electromechanical energy conversion | 51 |
| 2.4. Continuous energy conversion | 55 |
| 2.5. Non-salient and salient poles | 55 |
| 2.6. Notion of pole pitch | 58 |
| 2.7. Stator/rotor coupling: the “basic machine” | 59 |
| 2.8. Losses within the machines | 69 |
| 2.8.1. Losses due to Joule effect (or “Joule losses”). | 69 |
| 2.8.2. Electromagnetic losses (or “iron losses”) | 70 |
| 2.8.3. Mechanical losses | 70 |
| 2.9. Nominal values | 70 |
| 2.10. General sign covenant. | 71 |
| 2.11. Establishment of matricial equations. | 71 |
| 2.11.1. Working assumptions. | 72 |
| 2.11.2. Expression of the instantaneous torque. | 72 |
| 2.11.3. Continuous energy conversion in cylindrical machines | 74 |
| 2.11.4. Continuous energy conversion in salient pole machines. | 77 |
| 2.12. Mechanical equation. | 79 |
| 2.13. Conclusion | 80 |
| Chapter 3. Synchronous Machines. | 81 |
| 3.1. Introduction | 81 |
| 3.2. Introduction and equations of the cylindrical synchronous machine | 82 |
| 3.2.1. General description | 82 |
| 3.2.2. Why synchronous? | 85 |
| 3.2.3. Rotation speeds at constant frequency | 88 |
| 3.2.4. Equations of the cylindrical machine | 88 |
| 3.3. Analysis of the synchronous machine connected to an infinite power network | 93 |
| 3.3.1. Phasor diagram | 93 |
| 3.3.2. Active (P) and reactive (Q) graduation of the voltage diagram. | 94 |
| 3.3.3. “Internal” powers | 96 |
| 3.3.4. Stability of the synchronous machine | 100 |
| 3.3.5. V-curves called “Mordey curves” | 106 |
| 3.3.6. Case when resistance R is negligible | 110 |
| 3.4. Considerations about the salient pole synchronous machine | 111 |
| 3.4.1. Torque and inductance matrix. | 112 |
| 3.4.2. Calculation of the flux | 113 |

| | |
|---|------------|
| 3.4.3. Electrical equation and phasor diagram | 118 |
| 3.4.4. Calculation of the torque and stability analysis | 120 |
| 3.5. Consideration about permanent magnet machines. | 122 |
| 3.5.1. Surface permanent magnets machines | 123 |
| 3.5.2. Machines with inserted magnets | 124 |
| 3.5.3. Machines with embedded magnets. | 125 |
| 3.5.4. Modeling of permanent magnet machines | 128 |
| 3.5.5. Cylindrical machine modeling | 130 |
| 3.6. Inverted AC generators. | 137 |
| 3.7. Implementation of synchronous machines | 138 |
| 3.7.1. Implementation of synchronous motors. | 138 |
| 3.7.2. Implementation of the AC generators taking into account the saturation phenomena. | 150 |
| 3.8. Experimental determination of the parameters. | 164 |
| 3.8.1. Cylindrical machine in linear state | 164 |
| 3.8.2. Saturation of the cylindrical machine. | 164 |
| 3.8.3. Salient poles machine | 165 |
| Chapter 4. Induction Machines | 167 |
| 4.1. Introduction | 167 |
| 4.2. General considerations | 168 |
| 4.2.1. Structures | 168 |
| 4.2.2. Working principle | 172 |
| 4.3. Equations. | 173 |
| 4.3.1. Main notations | 173 |
| 4.3.2. Sign covenants and working assumptions | 174 |
| 4.3.3. Conventional representation. | 175 |
| 4.3.4. Flux analysis | 175 |
| 4.3.5. Electrical equations. | 179 |
| 4.3.6. Change in the sign covenant | 180 |
| 4.4. Equivalent circuits. | 181 |
| 4.5. Induction machine torque | 183 |
| 4.5.1. Instantaneous torque. | 183 |
| 4.5.2. Analysis of the energy transfer | 185 |
| 4.5.3. Expression of the electromagnetic torque in terms of the slip | 187 |
| 4.6. Study of the stability | 189 |
| 4.7. Circle diagram (or “Blondel” diagram) | 192 |
| 4.7.1. Introduction. | 192 |
| 4.7.2. g and in $1/g$ graduation of the circle | 193 |
| 4.7.3. Simplified circle diagram | 195 |
| 4.8. Induction machine characteristics. | 200 |

| | |
|--|------------|
| 4.9. Implementation of induction machines | 205 |
| 4.9.1. Motor mode | 205 |
| 4.9.2. Generator mode | 217 |
| 4.9.3. Single-phase induction motor | 225 |
| 4.10. Principle of the experimental determination of the parameters | 234 |
| 4.10.1. Case of wound rotor induction machines | 234 |
| 4.10.2. Case of cage induction machines | 235 |
| Chapter 5. Direct Current Machines | 237 |
| 5.1. Introduction | 237 |
| 5.2. Main notations | 238 |
| 5.3. DC machine structure. | 238 |
| 5.3.1. Constituents | 238 |
| 5.3.2. Analysis of the field winding. | 242 |
| 5.3.3. Analysis of the armature winding | 244 |
| 5.4. DC machine equations | 252 |
| 5.4.1. Hypotheses and covenants | 252 |
| 5.4.2. Equations | 252 |
| 5.4.3 Determination of the parameters | 256 |
| 5.5. Separately excited motor. | 258 |
| 5.5.1. Introduction. | 258 |
| 5.5.2. External characteristics | 260 |
| 5.5.3. Energy recovery: generator operating. | 265 |
| 5.6. Series excited motor | 269 |
| 5.6.1. Introduction. | 269 |
| 5.6.2. External characteristics | 271 |
| 5.7. Special case of the series motor: the universal motor | 274 |
| 5.8. Commutation phenomena | 274 |
| 5.9. Saturation and armature reaction. | 278 |
| 5.10. Implementation of DC motors. | 279 |
| 5.10.1. Constant voltage implementation. | 280 |
| 5.10.2. Present implementation of DC motors. | 284 |
| Bibliography. | 287 |
| Index | 289 |