

Table of Contents

Introduction	xiii
Acknowledgements	xvii
Chapter 1. Some Basic Notions About Powder Diffraction	1
1.1. Crystallite, grain, polycrystal and powder	1
1.2. Bragg's law and harmonic reflections	2
1.2.1. Bragg's law	2
1.2.2. Monochromator	3
1.2.3. Harmonic radiation components	3
1.3. Geometric conditions of diffraction, Ewald sphere	4
1.4. Imperfect powders	5
1.5. Main diffraction line profile components	6
1.5.1. Origin of $g(x)$	7
1.5.2. Origin of $f(x)$	9
1.5.3. Deconvolution-extraction of $f(x)$ and $g(x)$	10
1.6. Peak profile parameters	11
1.7. Modeling of the diffraction peaks	11
1.7.1. Why do we need modeling?	11
1.7.2. Modeling of a powder diffraction pattern	12
1.8. Experimental geometry	22
1.8.1. Curved Position Sensitive detector, asymmetric reflection geometry	22
1.8.2. CCD or image plate detector, transmission geometry	23
1.8.3. Curved-Area Position-Sensitive detector, transmission geometry	24
1.9. Intensity calibration (flat-field)	26
1.9.1. Counts and intensity	26

1.9.2. Flat-field	29
1.9.3. PSD detector	29
1.9.4. CAPS detector	30
1.10. Standard samples	32
1.10.1. Laboratory x-ray standards	32
1.10.2. Neutron texture standards	34
1.11. Probed thickness (penetration depth)	36
Chapter 2. Structure Refinement by Diffraction Profile Adjustment (Rietveld Method)	41
2.1. Principle of the Rietveld method	41
2.2. Rietveld-based codes	43
2.3. Parameter modeling	44
2.3.1. Background modeling	44
2.3.2. Structure factor	47
2.3.3. Crystallites' preferred orientation (texture) corrections	53
2.3.4. Peak asymmetry	57
2.3.5. Peak displacements	59
2.3.6. Lorentz-polarization correction	60
2.3.7. Volume, absorption, thickness corrections	62
2.3.8. Localization corrections	66
2.3.9. Microabsorption/roughness corrections	68
2.3.10. Wavelength	70
2.4. Crystal structure databases	71
2.5. Reliability factors in profile refinements	71
2.6. Parameter exactness	75
2.7. The Le Bail method	75
2.8. Refinement procedures	76
2.8.1. Least squares	76
2.8.2. Genetic or evolutionary algorithms	78
2.8.3. Derivative difference minimization (DDM)	80
2.8.4. Simulated annealing	80
2.9. Refinement strategy	81
2.10. Structural determination by diffraction	82
2.10.1. The phase problem in diffraction	82
2.10.2. Patterson function	83
2.10.3. Direct methods	84
2.10.4. Direct space methods	87
2.10.5. Fourier difference map	87
2.10.6. Extension to aperiodic structures	88

Chapter 3. Automatic Indexing of Powder Diagrams	91
3.1. Principle	91
3.2. Dichotomy approach	92
3.3. Criteria for quality	93
Chapter 4. Quantitative Texture Analysis	95
4.1. Classic texture analysis	95
4.1.1. Qualitative aspects of texture analysis	95
4.1.2. Effects on diffraction diagrams	98
4.1.3. Limitations of classic diagrams	102
4.1.4. The Lotgering factor	106
4.1.5. Representations of textures: pole figures	107
4.1.6. Localization of crystallographic directions from pole figures	121
4.1.7. Texture types	126
4.2. Orientation distribution (OD) or orientation distribution function (ODF)	131
4.2.1. Pole figures and orientation spaces	131
4.2.2. The orientation space \mathcal{H}	132
4.2.3. Euler angle conventions	133
4.2.4. Orientations and pole figures	135
4.2.5. Choice for the sample co-ordinate system K_A	136
4.2.6. Pole figure, crystal, texture and sample symmetries	139
4.2.7. Orientation distance	139
4.3. Distribution density and normalization	140
4.4. Direct and normalized pole figures	140
4.4.1. Direct experimental pole figures	140
4.4.2. Normalized pole figures	141
4.5. Reduced pole figures	143
4.6. Fundamental equation of quantitative texture analysis	143
4.6.1. Fundamental equation	143
4.6.2. Typical OD components	144
4.6.3. OD plotting	147
4.6.4. Finding an orientation component in the OD	149
4.7. Resolution of the fundamental equation	150
4.7.1. ODF and OD	150
4.7.2. Generalized spherical harmonics	150
4.7.3. Vector method	155
4.7.4. Williams-Imhof-Matthies-Vinel (WIMV) method	155
4.7.5. Arbitrarily-defined cells (ADC) method	157
4.7.6. Entropy maximization method	157
4.7.7. Component method	158
4.7.8. Exponential harmonics	159

4.7.9. Radon transform and Fourier analysis	160
4.7.10. Orientation space coverage	160
4.8. OD refinement reliability estimators	161
4.8.1. RP factors	161
4.8.2. RPw surface weighted factors	163
4.8.3. RB Bragg-like factors	164
4.8.4. RBw Bragg-like weighted factors	165
4.8.5. Rw weighted factors	165
4.8.6. Visual inspection	166
4.9. Inverse pole figures	168
4.9.1. Definition	168
4.9.2. Inverse pole figure sectors.	168
4.10. Texture strength factors	170
4.10.1. Texture index	170
4.10.2. Texture entropy	171
4.10.3. Pole figure and ODF strengths	171
4.10.4. Correlation between F^2 and S	171
4.11. Texture programs	173
4.11.1. Berkeley texture package (BEARTEX)	173
4.11.2. Material analysis using diffraction (MAUD)	173
4.11.3. General structure analysis system (GSAS)	173
4.11.4. Preferred orientation package, Los Alamos (popLA)	174
4.11.5. Texture analysis software (LaboTex)	174
4.11.6. Pole figure interpretation (POFINT)	174
4.11.7. Strong textures (STROTEX and Phiscans)	175
4.11.8. STEREOPOLE	175
4.11.9. MTEX.	175
4.12. Limits of the classic texture analysis	176
4.13. Magnetic quantitative texture analysis (MQTA)	178
4.13.1. Magnetization curves and magnetic moment distributions	178
4.13.2. A simple sample holder for MQTA	179
4.13.3. Methodology	179
4.13.4. From magnetic-scattering to the MODF and magnetic moment distributions	186
4.13.5. One example	186
4.14. Reciprocal space mapping (RSM)	189
Chapter 5. Quantitative Microstructure Analysis	191
5.1. Introduction.	191
5.2. Microstructure modeling (classic)	192
5.2.1. Integral Breadth, FWHM, volume- and area-weighted sizes	192
5.2.2. Scherrer approach.	195

5.2.3. Stokes and Wilson microstrains	196
5.2.4. Williamson-Hall approach	196
5.3. Bertaut-Warren-Averbach approach (Fourier analysis)	197
5.3.1. Instrumental contribution removal	197
5.3.2. Broadening due to crystallite size	198
5.3.3. Crystallite size and microdistortion broadening	199
5.3.4. Fourier analysis to integral breadths	201
5.3.5. Integral breadths to distributions, sizes and microstrains.	202
5.3.6. Relationships between $\langle R_A \rangle$ and $\langle R_V \rangle$	203
5.4. Anisotropic broadening: the Popa approach.	204
5.4.1. Anisotropic broadening	204
5.4.2. Anisotropic crystallite sizes	205
5.4.3. Anisotropic microstrains.	211
5.5. Stacking and twin faults	212
5.5.1. From Line shifts and Fourier analysis.	212
5.5.2. Popa approach.	214
5.6. Dislocations	214
5.6.1. Dislocation density	215
5.6.2. Wilkens' model and Fourier analysis	215
5.7. Crystallite size distributions	217
5.7.1. Normal size distribution function	217
5.7.2. Lognormal distribution function	217
5.7.3. Gamma distribution function	218
5.7.4. Anisotropic distribution functions	218
5.8. Rietveld approach	219
5.8.1. Constant wavelength data	219
5.8.2. Time of flight (TOF) neutrons	220
Chapter 6. Quantitative Phase Analysis	221
6.1. Standardized experiments	221
6.2. Polycrystalline samples.	221
6.3. Amorphous-crystalline aggregates	223
6.3.1. Crystallinity fraction	223
6.3.2. Amorphous modeling	224
6.4. Detection Limit	225
Chapter 7. Residual Strain-Stress Analysis	227
7.1. Strain definitions.	227
7.2. ϵ_{33} strain determination	229
7.2.1. Isotropic polycrystalline sample	229
7.2.2. Single crystal	229
7.3. Complete strain tensor determination	230

7.3.1. Isotropic polycrystalline samples	230
7.3.2. Single crystal samples	231
7.4. Textured samples	232
7.4.1. Introduction	232
7.4.2. Non-linear least-squares fit	233
7.4.3. Strain and stress distribution functions	234
Chapter 8. X-Ray Reflectivity	235
8.1. Introduction.	235
8.1.1. Definition of the reflectivity	235
8.1.2. Specular and off-specular reflectivity	236
8.1.3. Combined specular and off-specular scans	237
8.2. X-rays and neutrons refractive index	238
8.2.1. X-rays.	238
8.2.2. Neutrons	239
8.3. The critical angle of reflection.	240
8.3.1. X-rays.	240
8.3.2. Neutrons	241
8.4. Fresnel formalism (specular reflectivity)	241
8.4.1. Reflection coefficient and reflectivity	241
8.4.2. Transmission coefficient.	244
8.4.3. Yoneda wings	245
8.5. Surface roughness	246
8.5.1. Roughness representation	246
8.5.2. Single layer on a substrate.	249
8.6. Matrix formalism (specular reflectivity)	250
8.7. Born approximation	251
8.8. Electron density profile	251
8.9. Multilayer reflectivity curves	252
8.10. Instrumental corrections	253
8.10.1. Correction for an irradiated area	253
8.10.2. Imperfectly parallel beam	254
Chapter 9. Combined Structure-Texture-Microstructure-Stress-Phase Reflectivity Analysis	257
9.1. Initial queries	257
9.2. Implementation	261
9.3. Experimental set-up	264
9.4. Instrument calibration.	264
9.4.1. Peak broadenings	266
9.4.2. Peak shifts	269
9.4.3. Background variations	269

9.5. Refinement strategy	269
9.5.1. Global scheme.	269
9.5.2. Solution examination.	271
9.6. Examples	272
9.6.1. QTA of single-phased materials	272
9.6.2. QTA and isotropic QMA	297
9.6.3. Anisotropic crystallite shape, texture, cell parameters, and thickness	300
9.6.4. Layering, isotropic shape, microstrains, texture, and structure	307
9.6.5. Phase and texture	311
9.6.6. Texture of modulated structures	334
9.6.7. Texture, residual stresses and layering	341
9.6.8. Texture and structure.	346
Chapter 10. Macroscopic Anisotropic Properties	363
10.1. Aniso- and isotropic samples and properties.	363
10.2. Macroscopic/microscopic properties	364
10.2.1. \bar{v}^M and \bar{v} tensors	364
10.2.2. Microscopic properties.	364
10.2.3. Macroscopic properties anisotropy and modeling	413
Bibliography	441
Glossary	483
Abbreviations	487
Mathematical Operators	489
Index	491