

## Table of Contents

<b>Foreword</b> . . . . .	xi
<b>Preface</b> . . . . .	xiii
<b>Chapter 1. Surfaces</b> . . . . .	1
1.1. Introduction . . . . .	1
1.2. The surface state . . . . .	2
1.2.1. Structural state of a surface . . . . .	2
1.2.2. Topographic state of a surface . . . . .	3
1.2.2.1. Atomic-scale topographic state . . . . .	4
1.2.2.2. Micrometer-scale topographic state . . . . .	5
1.2.2.3. Experimental techniques . . . . .	9
1.2.3. Surface energy . . . . .	18
1.2.3.1 Surface energy measurements . . . . .	21
1.2.4. Mechanical state of a surface . . . . .	24
1.2.4.1. Hardness . . . . .	24
1.2.4.2. Young's modulus . . . . .	27
1.2.4.3. Nano-indentation . . . . .	30
1.2.4.4. Fracture toughness . . . . .	34
1.2.4.5. Residual stresses . . . . .	37
1.2.5. Chemical composition of a surface . . . . .	43
1.2.5.1. Energy dispersive X-ray analysis . . . . .	44
1.2.5.2. X-ray photoelectron spectroscopy . . . . .	45
1.2.5.3. Auger electron spectroscopy . . . . .	45
1.2.5.4. Glow discharge optical emission spectroscopy . . . . .	45
1.2.5.5. Rutherford backscattering spectroscopy . . . . .	46
1.2.5.6. Secondary ion mass spectroscopy . . . . .	46
1.2.5.7. Infrared spectrometry . . . . .	47

<b>Chapter 2. Tribology</b> . . . . .	49
2.1. Introduction. . . . .	49
2.2. Elements of solid mechanics. . . . .	50
2.2.1. The stress vector . . . . .	50
2.2.2. The stress tensor . . . . .	50
2.2.3. Yield criteria . . . . .	52
2.2.3.1. The Tresca criterion . . . . .	52
2.2.3.2. The von Mises criterion . . . . .	53
2.3. Elements of contact mechanics . . . . .	53
2.3.1. Hertz contact theory . . . . .	53
2.3.2. The contact area . . . . .	57
2.3.3. Plastification of asperities . . . . .	59
2.3.4. Adhesive contact . . . . .	59
2.4. Friction . . . . .	62
2.4.1. The coefficient of friction . . . . .	62
2.4.2. Tribometers . . . . .	66
2.4.3. Laws and theories of friction. . . . .	68
2.5. Nanotribology . . . . .	71
2.5.1. Surface forces . . . . .	71
2.5.1.1. Electrostatic forces. . . . .	71
2.5.1.2. Capillary forces. . . . .	71
2.5.1.3. Van der Waals forces . . . . .	72
2.5.2. Surface forces measurements . . . . .	75
2.5.2.1. The surface forces apparatus (SFA). . . . .	75
2.5.2.2. The atomic force microscope (AFM). . . . .	76
2.5.2.3. Application: surface forces and micromanipulation . . . . .	79
2.5.3. Nanofriction . . . . .	81
2.6. Wear . . . . .	82
2.6.1. The different forms of wear . . . . .	83
2.6.1.1. Adhesive wear . . . . .	83
2.6.1.2. Abrasive wear. . . . .	83
2.6.1.3. Fatigue wear . . . . .	83
2.6.1.4. Tribochemical wear . . . . .	83
2.6.2. Wear maps . . . . .	84
2.6.3. Interface tribology: third body concept. . . . .	86
2.6.4. The PV product. . . . .	88
2.7. Lubrication . . . . .	89
2.7.1. Oils. . . . .	89
2.7.1.1. The notion of viscosity . . . . .	89
2.7.1.2. The viscosity index and the SAE standard . . . . .	90
2.7.1.3. The Stribeck curve. . . . .	91
2.7.1.4. The different types of oils. . . . .	92

2.7.1.5. Greases . . . . .	94
2.7.1.6. Anti-friction materials . . . . .	94
2.8. Wear-corrosion: tribocorrosion and erosion-corrosion . . . . .	98
2.8.1. Tribocorrosion . . . . .	99
2.8.2. Erosion-corrosion . . . . .	106
<b>Chapter 3. Materials for Tribology . . . . .</b>	<b>109</b>
3.1. Introduction . . . . .	109
3.2. Bulk materials . . . . .	110
3.2.1. Metallic materials . . . . .	110
3.2.1.1. Iron-based alloys . . . . .	110
3.2.1.2. Superalloys . . . . .	112
3.2.1.3. Copper-based alloys . . . . .	113
3.2.2. Polymers . . . . .	113
3.2.2.1. High-density polyethylene . . . . .	115
3.2.2.2. Fluorinated polymers . . . . .	115
3.2.2.3. Polyacetal (polyoxymethylene: POM) and polyamide . . . . .	116
3.2.2.4. Polyimide . . . . .	116
3.2.2.5. Polyetheretherketone (PEEK) . . . . .	116
3.2.2.6. Friction and wear of polymers . . . . .	117
3.2.2.7. Surface treatment of polymers . . . . .	118
3.2.3. Composites . . . . .	120
3.2.3.1. Friction materials . . . . .	121
3.2.4. Ceramics . . . . .	121
3.2.4.1. Friction and wear of ceramics . . . . .	126
3.2.5. Cermets . . . . .	131
3.2.5.1. Tungsten-carbide (WC)-based cermets . . . . .	132
3.2.5.2. Other carbide-based cermets . . . . .	133
3.3. Surface treatments and coatings . . . . .	133
3.3.1. Conversion techniques . . . . .	134
3.3.1.1. Anodic oxidation . . . . .	134
3.3.1.2. Ion implantation . . . . .	137
3.3.1.3. Ion beam mixing . . . . .	142
3.3.1.4. Thermochemical treatment . . . . .	143
3.3.1.5. Transformation hardening . . . . .	143
3.3.1.6. Mechanical treatment . . . . .	144
3.3.2. Deposition techniques . . . . .	146
3.3.2.1. Thermal projection techniques . . . . .	147
3.3.2.2. Liquid-phase deposition techniques . . . . .	148
3.3.2.3. Vapor-phase deposition techniques . . . . .	154
3.4. Hard anti-wear and decorative coatings . . . . .	166

3.4.1. Hard anti-wear coatings. . . . .	166
3.4.1.1. Transition metal nitrides . . . . .	166
3.4.1.2. Carbon-based films . . . . .	171
3.4.1.3. The role of the substrate. . . . .	173
3.4.2. Decorative coatings . . . . .	174
3.5. Characterization of coatings : hardness, adherence and internal stresses . . . . .	178
3.5.1. Hardness . . . . .	178
3.5.1.1. The indentation size effect . . . . .	179
3.5.1.2. Hardness tests for coated materials . . . . .	180
3.5.2. Coating adhesion . . . . .	190
3.5.2.1. Methods for adherence testing . . . . .	192
3.5.3. Residual stresses in coatings . . . . .	201
3.5.3.1. Origin of internal stresses. . . . .	201
3.5.3.2. Determining residual stresses upon X-ray diffraction . . . . .	202
3.5.3.3. Determining internal stresses by radius of curvature measurements (Stoney's method) . . . . .	202
<b>Bibliography</b> . . . . .	205
<b>Index</b> . . . . .	223